

**HACKETTSTOWN REGIONAL MEDICAL CENTER
CARDIO PULMONARY POLICY MANUAL
ADENOSINE NUCLEAR STRESS TEST**

=====

Effective Date: June 2001
Cross Referenced:
Reviewed Date: 02/16
Revised Date: 02/16

Policy No: 8B.006
Origin: Cardio Pulmonary
Authority: Cardio/Pulmonary Manager
Page: 1 of 3

Purpose: A nuclear exercise stress test is ordered by the physician to evaluate the blood flow of the heart when it is required to work under stress.

Resources:

1. GE Case V 6.01 Exercise Testing System (Stress Computer)
2. Electrodes
3. Alcohol Wipes
4. Rescue Kit
5. Skin Prep with abrasion pad
6. Consent Form
7. Adenosine Vital Sign Record
8. Blood Pressure machine and stethoscope
9. MUSE Cardiology Information System

Personnel:

1. Cardiology Technician
2. Attending Cardiologist to be determined by the ordering physician
3. Nuclear Medicine Technician

Contraindications:

1. Patients with the following:
 - o recent (1 week) myocardial infarction
 - o unstable angina
 - o significant aortic stenosis
 - o obstructive cardiomyopathy
 - o atrial tachyarrhythmias with uncontrolled ventricular response
 - o history of ventricular tachycardia
 - o uncontrolled hypertension
 - o thoracic aortic aneurysm
 - o left bundle branch block

Pre-procedural Requirements:

- Patient should be fasting for at least eight (8) hours other than morning medications taken with sips of water.
- The following medications should be held unless otherwise specified by the patient's physician: beta blockers, isorbide dinitrate and isorbide mononitrate.
- Diabetics should not take insulin that will peak during this time.
- Nitroglycerin patches should be removed on hour prior to stress test
- An accurate weight must be done at the time of the test.

Procedure: The following is done by the cardiology technician:

1. Introduce yourself to the patient and confirm patient by asking for two identifiers i.e.: first and last name, spelling of the last name, and date of birth.
2. Confirm written order is correct.
3. Obtain written consent from the patient.

**HACKETTSTOWN REGIONAL MEDICAL CENTER
CARDIO PULMONARY POLICY MANUAL
ADENOSINE NUCLEAR STRESS TEST**

=====

Effective Date: June 2001
Cross Referenced:
Reviewed Date: 02/16
Revised Date: 02/16

Policy No: 8B.006
Origin: Cardio Pulmonary
Authority: Cardio/Pulmonary Manager
Page: 2 of 3

4. Obtain the patient's medical history, height, weight, and list of current medications and using this information complete the top portion of the Adenosine Vital Sign Record.
5. After patient's privacy is secured, prep the chest using the following technique:
 - Shave any hair present
 - Clean area using alcohol wipes
 - Rub abrasive pad over area
6. Apply ten (10) disposable electrodes to the chest of the patient in the following areas:
 1. One on each clavicle area (LA and RA).
 2. One on each lower ribcage area (LL and RL).
 3. V1 placed at the right border of the sternum at the 4th intercostal space.
 4. V2 placed at the left border of the sternum at the 4th intercostal space.
 5. V3 midway between V2 and V4.
 6. V4 placed at the intersection of the mid-clavicular line and the 5th intercostal space.
 7. Midway between V4 and V6.
 8. V6 placed at the anterior axillary line on the same horizontal level as V4.
7. Obtain a resting blood pressure.
8. At this time the patient will be placed under the Nuclear Medicine camera by the Nuclear Medicine Technician for resting images.
9. Enter patient data into the CASE stress computer including all of the following information: patient name, ID number (Medical Record #-- 9 digits), date of birth, Gender, height, weight, past medical history, test indication, ordering physician, attending physician, technician initials and MUSE logon number, Order # (**9 digits**—for example **0234567891**, current medications, test to be performed and Adenosine test protocol.
10. When the resting images are completed, notify the attending cardiologist that the patient is ready for the test.
11. Assist the patient to the stretcher in the Nuclear Stress Lab.
12. Attach ten (10) EKG wires to the electrodes on the chest of the patient.
13. Attach the automatic blood pressure cuff and pulse oximeter to the patient.
14. Provide oxygen at two (2) liters via nasal cannula to the patient.
15. On the CASE stress computer, press "Pretest".
16. Press "Enter BP" and enter the resting blood pressure.
17. Press "12-lead". The supine EKG will print.
18. When the attending cardiologist arrives, obtain the cardiologist's signature on the informed consent. Inform the nuclear medicine tech to begin the Adenosine injection.
19. When instructed by the cardiologist, press "exercise". The Adenosine protocol will begin.
20. Set the automatic blood pressure cuff to obtain the patient's blood pressure every two minutes. Enter the blood pressure into the CASE stress computer each time the prompt to do so appears.
21. Record the patient's heart rate and pulse oximetry every minute and blood pressure every two minutes on the Adenosine Vital Sign Record.
22. Monitor the patient's EKG tracing, heart rate and blood pressure until all are within normal limits or close to the patient's resting baseline. At this time, press "test end".
23. Click on "Print Report". The final report will print. The final report and a copy of the Adenosine Vital Sign Record are given to the Nuclear Medicine Technician.

**HACKETTSTOWN REGIONAL MEDICAL CENTER
CARDIO PULMONARY POLICY MANUAL
ADENOSINE NUCLEAR STRESS TEST**

=====

Effective Date: June 2001
Cross Referenced:
Reviewed Date: 02/16
Revised Date: 02/16

Policy No: 8B.006
Origin: Cardio Pulmonary
Authority: Cardio/Pulmonary Manager
Page: 3 of 3

24. Disconnect all leads and remove electrodes from the patient except the two arm leads and left leg lead.
25. Completed consent (ensuring each signature is dated and timed using military time) and Adenosine Vital Sign Record is placed in the patient's chart (for inpatients) or sent to Medical Records (for outpatients). A copy of the patient's face sheet is put in the EKG room with the name of the test done and attending cardiologist's name at the top.

Transfer test to MUSE

1. When all stress tests are completed for the day, return to initial screen in CASE.
2. Click on "Local Database".
3. Click on the blue "Examinations" box.
4. Click "Select Today's Date". The remaining list of patients will be the tests done that day.
5. Click the first name listed. Hold the shift key down and click the last name listed. All the names should turn blue.
6. Click "Transfer to MUSE".
7. Click "Save".
8. Click "Initial Screen".
9. Click "End Program". The CASE stress computer will shut down.

Editing test in MUSE

1. Log into the MUSE Cardiology Information System.
2. Click on "Stress Tests".
3. Chose the desired stress to be edited by double clicking on the patient's name.
4. Review all demographic information. Edit as needed.
5. Select the overreader (the cardiologist who attended the stress test).
6. Click on "Demographic Complete/Send to Inbasket" (Icon of a doctor and a check mark).